

# New York Residential Existing Homes Programs

Quality Assurance Contractor Scoring System: A User Guide for Participating Contractors

May 2019

# **Table of Contents**

- 1. Log-in Page/Forgot Password
- 2. Dashboard
- 3. RSVP
- 4. View/Respond to Inspection Reports
- 5. Reports
- 6. Glossary
- 7. FAQ

## Login Page/Forgot Password

Initially, you are sent an email from NYSERDA with your username and temporary password. The email includes the following link: <u>https://cris.nyserda.org/qacss/Login.aspx.</u> Click on the link to continue.

When logging in to the Quality Assurance Contractor Scoring System (QACSS) for the first time, the system prompts you to create a new password. If you forget your password, click on the Forgot Password? link and the password is forwarded to your login email account.

/ :	A . @ #
e  ightarrow C [ $*$ https://crk.nyseda.org/qxssl/.ogin.apx	् १ 🖈 🖬 🗄
NYSERDA Quality Assurance Contractor Scoring System	
Usemame *	
Password *	
Looin Reset	
Login	
Forgot Password?	
© 2015 - 2016 NYSERDA	
If you forget your personal pliels	
in you lorger your password, click	
on this link and the system emails	
the password to your OACSS email	

# Dashboard

Once logged in, you are directed to the Dashboard page, which provides quick views to tasks that need attention.

The main section of the Dashboard page includes inspection reports requiring corrective action as well as a list of upcoming inspections that need an RSVP to attend.

The left menu includes links that navigate to all available pages in QACSS.

If you participate in both Home Performance with ENERGY STAR<sup>®</sup> and EmPower you can toggle between each program to view relevant QA information by clicking the drop-down box in the upper right-hand corner of your screen.

To the left of the program drop-down box in the upper right-hand side of the screen is a bell icon which displays quick notifications to new inspection reports, RSVPs required, and messages from program.



### **RSVP**

At the time of scheduling, the customer is asked if the contractor can attend the inspection. In most cases, the customer agrees. Once the customer agrees, an email is dispatched requesting that the contractor log in to QACSS and RSVP.

To RSVP, click on the blue button next to the customer name on the Dashboard screen. The RSVP Needed section lists scheduled inspections that require a response.

NEW YORK NYSERDA	0						🐀 🛪 🗮 EmDower x 🔮	
Control Contro	Quality	Assurance Contra	ctor Scoring System	n				
	(11)							
HOME	/ Home / L	Jashboard	-			-		
Dashboard			0			U	$\overline{\mathcal{R}}$	
MY WORK LIST		Corrective Action F	Report		Dverdue Corrective A	ction Report	RSVP N	eeded
Corrective Action Reports								
Job Score Reports	Corre	ective Action Report	^	Overd	ue Corrective Action	Report ^	RSVP Needed	^
RSVP Status	5 v rec	ords per pageearch:		5 v reco	ords per pag@earch:		5 • records per pageearch	
CLOSED WORK LIST								
Closed QA Reports	Status	Customer Name	Inspection Date	Status	Customer Name	Inspection Date	Customer Name	Action
REPORTS		Douglas	10/21/2016		Laurel	05/25/2016	D03	RSVP
QA Performance Report		D03	10/18/2016	Showing 1 to	1 of 1 entries		DO:	RSVP
Inspection Metrics Report		John S		1997-1997 <b>-</b> 1997	- Previous 1	Noxt	Dage	-
CAR Status Report		D01 Hazel/Helen	09/26/2016	Derne	ndad		Melinda	RSVP
My Schedule				Respo	nse Needed		D03	RSVP
EEDBACK/QUESTIONS		Carrie	10/03/2016				Briney	
Submit Feedback/Question		D036	09/26/2016				Showing 1 to 4 of 4 entries	
View Response		Gene					← Previous	1 Next-+
	Showing 1 t	o 5 of 5 entries						
		+- Previous 1	Next					
	Rospo	onded						

After clicking the RSVP button, the following pop-up appears requesting a contact name and number. The QA inspector uses this information if there are last minute changes to the inspection.

/(# == Q4CSS .== X							800
$\leftrightarrow$ $\supset$ $\mathbf{C}$ $\begin{bmatrix} \mathbf{a} \ https://cris.nyserda.org/qacss/Max$	inDashboard.aspx						९ 🖈 🗖
	SERDA	Quality As:	surance Cont	ractor Scoring System	💌 🔳 EmPe	ower - 👤 Town Build	
		More Inform	nation				
	/ Home	Customer In	nformation	Inspection Informat	tion		
		Flora		t and the second se			
	с	Buffalo New York	( 14208	11/3/2016 1:30 PM		RSVP Nee	
		RSVP Infor	mation			4	
	Cor					RSVP Needed	^
	5 \$6	Attendee Name				Seatebids per	
	page	Attendee Cell	<u></u>			Sustamer Name	
	Status	RSVP	Select •			36578792	
						- ira Henderson	
				Save	Close	36579815 mes Coster	
		John Stineman	1011012010	Showing 1 to 1 of 1 entries		D036491029	

You may edit the RSVP status up until the time of the inspection. To change contact information or status for the inspection, click on the left menu link titled RSVP Status.

NYSERDA	Quality Ass	urance Contra	actor Scoring System	m			4	r ▼ III EmPower ▼	1	•
HOME	/ My Work List /	RSVP Status								
Dashboard	📑 RSVP - Ye	s								
MY WORK LIST	5 records	per page						Search		
Corrective Action Reports										
Job Score Reports	Project ID	Name	Customer Address	Inspection Date	Inspection Time	Attending	RSVP Attendee Name	RSVP Attendee Cell	Project Document	Action
RSVP Status	D0365	Flora	1 Blvd Lowr	11/03/2016	1:30 PM	Yes v	John Smith			Edit
CLOSED WORK LIST			Buffalo New York						è	-
Closed QA Reports										
REPORTS	Showing 1 to 1 of	1 entries								
QA Performance Report					- Provid	us 1 Next	-+			
Inspection Metrics Report										
CAR Status Report	TRSVP - No	0								
My Schedule					Click search for	the filter ( No records	found			
EEDBACK/QUESTIONS					1000 - 000 L 11 101	0-9 mile - 10/10/003				
Submit Feedback/Question										
And Balance										

## **Inspection Reports (Pass)**

Newly issued inspection reports that receive a score of three or higher may contain one or more deficiencies that need to be corrected, but the contractor is *not* required to submit a response to NYSERDA. The findings can be contested within 10 days of issuance.

To view the official report, click on the 🚎 icon.

To contest the inspection results, click on the blue Project Number link shown in the screen shot.

## **Inspection Reports (Fail)**

Inspection reports that receive a score of one or two contain one or more deficiencies that need to be corrected, and photo documentation needs to be uploaded. To view and respond to these reports, click on the left menu link titled, Open Fail Reports.

From this page you can view the official report by clicking the 🚎 icon.

To respond to the inspection, click on the blue Project Number link shown here:

/(# III. Q4CSS X								8	0 8 2
$\leftarrow$ $\rightarrow$ C $\blacksquare$ Secure   https://cris.nyserda.o	rg/qacss/ContractorOverAllCAR	List.aspx						Q, ·	☆ :
👯 Apps 🔺 Bookmarks 🛄 Imported From IE 🧦 G	QACSS Enrollment 👍 QACSS Produc	sion 📋 Contractor Tracking Sh 🚯 ASHP - CLEAResult 🗭 Si	elesforce - Dev 🛛 🗢 SQA UAT - Issues by S 👍 🕸 External User	rs - Enrolin 📋 Empire Knowledg	gebank 🚺 SiteCapture			or	ther bookmarks
NYSERDA Quality	Assurance Contractor S	coring System				- <b>-</b>	III EmPower - ;	L (	
HOME									
🛱 Dashboard	Open Fail Report							A Export to Excel	^
MY WORK LIST	Status	Select	• Fit	ter Reset					
Copen Fail Report	5 • records per page						Se	arch:	
Copen Pass Reports						Field Score	Failure		
RSVP Status	Status Project	ID Customer Name	Customer Address	QA Issued	Due Date	Field Score	Count	Quick View	
CLOSED WORK LIST	331	Shiney A	Syracuse 13209	03/22/2018	4/21/2018	2	2	🚝 🛋	
Issued QA Reports									
REPORTS	Showing 1 to 1 of 1 entries								
QA Performance Report	-		← Previous 1 1	NECI					
Open Fail Status Report	Response Needed	Responded							
Submit Feedback/Dueston	Overdue Open Fail	Report						🛓 Export to Excel	*
New Response	Status	famet		Dents					
RELOURCES		100.011	1	Reset					
💼 User Guide			Click search for the fiber / No rec	cords found					
	Response Needed	Responded							

© NYSERDA 2017 - 2018

Powered by: NYSERDA

Click on the link with the 😑 icon to respond. In the Contractor Response table, select Mark as Resolved or Contest Rating. In each case, photos and/or written documentation must be submitted. Be sure to click the blue save button and then the Submit to Program button. When a decision has been made on the item(s) contested, an email is sent requesting you to log in to QACSS to view the result(s).

- 1. Click on the hyperlink with an 🤤 icon.
- 2. Review the Inspection Data at top of the screen.
- 3. Choose Action: Mark as Resolved or Contest Rating.
- 4. Enter response in the Resolved Notes field under Contractor Response.
- 5. Upload photo(s) as attachments using the browse function Choose Files.
- 6. Click Save.
- 7. Repeat for all deficiencies requiring corrective action.
- 8. Return to top of the screen and click on Customer Signature Page.

C Secure   https://cris.nyserda.org/qacss/Pop	UpContestedCAR.aspx?SID=q4N2vR4hi4o=				Q \$
* Bookmarks Disported From IE C QACSS Enrolmer	e Contractor Scoring System	🕅 ASHP - CLEAResult 🗭 Salesforce - Dev 🔷 SQA UAT - Issue	s by S 🔅 External Users - Enrolin 🚹 Empire Knowledgeb	ank 🔯 SteCapture	📑 EmPower - 🏦 🛄 , Inc
E					
shboard Open I	Fail Report				
ORK LIST				_	
n Fail Report			View Project Documents		
in Pass Reports	tor Name R		View Field Report		
/P Status	er Addrees			_	
ED WORK LIST	New York 12096	man	Conversation with Program		
id QA Reports	n required				
RTS O Awat	ing decision by Program Implementer and/or QA Manager has been marked resolved by Program Implementer				
Performance Report	national Only				
n Fail Status Report	ta Collection				Collapse / Expand
nit Feedback/Question					
Response	Data Collection	ER. You must click the blue "Submit to Program" button at the bo	tom of the page for the Program implementer to be able to vi	sw and respond to your response.	
RCE1 B W	Previoting Conditions Accura Provide Previoting Conditions Accura Failure Des	icription	Attic insulation and/or air sealing *		
Gude	Shell Measures W Attic Insulation				
	Contruous Air Barrier Pre	Lion Data			·
	Chimney Chases Sealed Measure	Visual Inspection			
	Compussion Appliance Testing Task	Attic Space Accessible			
	Alte Source Accessible	wertchon Attack and an and an and an			
		hatch has been sealed at hatch has been sealed at ensure installed measure venification.	Access to the attic must be provided in order to are completed or pictures should be submitted for		
	Attachme	rt Preview	Notes		
		ATT I	Teo Small atles.		
	1 Contrac	ctor Response			
	Action	Select	•		
	Allachme 6t needed	171 Contest Rating D Mark As Resolved Note to Program			
					Save
					Submit to Program

QACSS stores all QA reports issued from July 15, 2015 going forward. To view final inspection reports, click on the left menu link Issued QA Reports. Under the Quick View column, view the final Inspection Report and the Corrective Action Response activity report (if applicable) by clicking on each icon: 🚋 📓.



© NYSERDA 2017 - 2018

Powered by: NYSERDA

## **Fail Inspections (Corrective Action Reports)**

A list of outstanding Failed Inspection Reports and their statuses can be found on your Dashboard page or by clicking Open Fail Reports in the left menu bar. To view and respond to a report, click on the blue Project Number hyperlink.

Inspection Reports that need responses are indicated by icons.

Inspection Reports that need a response from program representatives are indicated with a loon.

Inspection Reports that have been marked as resolved by your program representative are removed from the Open Fail Report list. An email is sent notifying you the report has been resolved.

(g in QACSS.ii) X								8	001
← → C 🔒 Secure   https://cris.nyserda	a.org/qacss/ContractorOverAllCARList.aspx							Q	☆ ③
🖬 Apps 🚖 Bookmarks 🔝 Imported From IE 🔅	QACSS Enrollment 🔅 QACSS Production 🗋 Co	ntractor Tracking Shi 🚯 ASHP - CLEAResult 🐡 Salesh	rce - Dev 🐡 SQA UAT - Issues by Sa 🔅 External U	isers - Enroli: 🗋 Empire Knowled	lgebank 🚺 SiteCapture			<mark> </mark> c	Other bookman
Qual	ity Assurance Contractor Scoring S	ystem					4 <sup>-1</sup> =	EmPower - 1 R	
HOME									
🕮 Dashboard	Open Fail Report							🛓 Export to Excel	^
MY WORK LIST	Status	Select		Filter Reset					
Open Pass Reports			Glick search for the filter / No	records found					
I RSVP Status	Response Needed Responder	1							
CLOSED WORK LIST	Overdue Open Fail Report							L Export to Excel	^
Issued QA Reports	Status	Select	1	Ellor Doset					
REPORTS	5 v records per pape		_	Photos				arth	
OA Performance Report	The second section is a second section of the second secon								
Open Fail Status Report	Status Project ID	Customer Name	Customer Address	QA Issued	Due Date	Field Score	Count	Quick View	
Submit Feedback/Question		Janice (	St	08/04/2017	9/9/2017	2	0	æ 🖬	
B. Mew Response			Hagaman New York 12095					-CO 181	
RESOURCES	Showing 1 to 1 of 1 entries								
Uner Guide	Response Needed 🎆 Responder	i .	- Previous 1	Nod					

6 NYSERDA 2017 - 2018

Powered by: NYBERDA

# Reports

QA Performance Report: Displays summary-level data on the number of completions within a user-specified time period and displays the average inspection score and sub-component scores.

Company Name     DBA     County     Status HP     Status ER     1M0     3 M0     12 M0     12 M0     JSR     Grade     A     WQ     HS     CS       Company Name     DBA     County     Status HP     Status ER     1M0     3 M0     12 M0     12 M0     JSR     Grade     A     WQ     HS     CS       Company Name     DBA     County     Status HP     Status ER     1M0     3 M0     12 M0     12 M0     JSR     Grade     A     WQ     HS     CS       Company Name     DBA     Toga     Full     Full     13     54     26     3     13     56     20     98     - 07     99     96     90	EmPow	er New	York	Per	forman	ice	Sun	nmar	ry R	еро	ort	کہ	NEW	YORK	N	/SER	DA	
Company Name       DBA       County       Status HP       Status ER       IMO       3 MO       12 MO       12 MO       JSR       Grade       AQ       WQ       HS       CS         Company Name       DBA       Toga       Full       Full       13       54       28       3       13       56       20       98       -       97       99       96       90         * Represents the avarage QA scores for the 12 months before QACSS went live on 07/01/2015.       ***********************************					S	epte	mbei	e: All r 2016					2 Depor	TUNITY.				
Company Name       DBA       County       Status HP       Status ER       1 M0       3 M0       1 2 M0       1 2 M0       JSR       Grade       AQ       WQ       HS       CS         Image: Status HP       Toga       Full       Full       13       54       28       3       13       56       20       98       -       99       96       90       90       96       90		Contractor In	formation			Co	ompleti	ons	In	spectio	ons	Inspection Rate		Average	Scores I 12 M	Based on onths	Rolling	I
Image       Traga       Full       Full       13       54       28       3       13       66       20       98       -       97       99       96       90         • Represents the avarage QA scores for the 12 months before QACSS went live on 0701/2015.	Company Name	DBA	County	Status HP	Status ER	1 MO	3 MO	12 MO	1 MO	3 MO	12 MO	12 MO	JSR	Grade	AQ	wq	HS	cs
* Represents the avarage QA scores for the 12 months before QACSS went live on 07/01/2015.	ties		Tioga	Full	Full	13	54	284	3	13	56	20	98		97	99	96	90
	* Represents the avarage	QA scores for the 12 m	onths before QACS	SS went live or	07/01/2015.													

Pareto Analysis Report: Displays the frequency of deficiencies within a user-specified time period and provides a bar graph of the deficiencies and frequency percentage. This data is useful to determine areas were installation changes/improvements could be beneficial.

- 1. Select Program from upper right dropdown.
- 2. Select the Project Type; default is all project types.
- 3. Select Number of Defects; 5, 10 or 15
- 4. Select Report Range Type; Month or Custom
  - a. Month report range; select month from dropdown
  - b. Custom report range; enter the report range
- 5. Open; select format from dropdown (PDF, Excel or Word)

New York NYSERDA	Quality Assurance Contractor Scoring	System	tar and the second sec
HOME	Pareto Analysis Report		1
MY WORK LIST Claim Fail Report Claim Open Plass Reports RSVP Status CLOSED WORK LIST Milliound OA Reports	Program Project Type Contractor Name Category Measure Category	EmPlower  Complexity Electric Reduction  Single Family Hone Performance  Multi Family Hone Performance  Freedom Mechanicali  All  Select an Option	
CA Performance Report CA Performance	Defect Level No of Defects (Top Deficiency) Report Range Type Inspection Date Range	Al • • 3 5 • • 4 1/1/2015 To 10/15/2015 4 5 ★ Open -	Reset

© NYSERDA 2017 - 2018

EmPov	ver Ne	ew York			NEW YORK STATE OF OFFORTUNITY.	ERD	A	EmPo	owe	er New York ک	NEW YORK STATE OF OPPORTUNITY.	NYSERDA
			1/	Pareto Analysis 1/2015 - 10/18/2018					20	Defect Court	100%	100
Contractor :												
Project Type :	All										All and a second se	80
Job Score Category	AB								15			
Measure Category :	AB											
Measure:	AE							122				60 j
Defect Level :	AL							Con	10			later
Job Score Category	Measure Category	Measure	Defect	Task Name	Task Requirement	Defect Count	% of top detects	đ.				
Work Quality	Deect install	Smoke Detector		Powered by Lithauts ballery	None	3	11.5 %			31%		~~ s
realth & Safety	Contrustion Appliance Testing	Visual Impection	CI	CAZ and Appliances Related Safety Issues Identified	Contractor should have identified and recommended a fit for any CA2 and Appliance related safety saster, including, defailed or corrodet flue pipes or problems with size or plich, problems with CHW relet wide, brown or kniked oil lines, water leakage, open returns, no ar filter, etc.	3	11.5%		5	22%		- 20
Health & Safety	Conduction Appliance Testing	Testing Inspection	Ct	Smoke Reading Acceptable	Smoke reading of fuel oil units within manufacturers specifications, typically be between 0-1	2	77%			12%		
Work Quality	Deect Install Measures	CO Defector		Powered by Lithium Batlery	None	2	77%		0	CA2 and Appliances Rolated Safety Insule Interther	Offens.	
Al	Ad	Al		Others	None	16	61.5 %			Inspection Elements		
				Total		26	100					

Powered by: NYSERDA

## Glossary

**QACSS:** The Quality Assurance Contractor Scoring System is a secured, web-based portal designed to facilitate quality assurance functions performed in the residential single-family programs. It is used by NYSERDA's third-party quality contractor to schedule, inspect, and report on completed field inspections and by participating contractors and program implementation staff to resolve issues documented by the quality contractor.

Dashboard: Main page or homepage where contractors navigate to other pages.

**Fail Report (Corrective Action Report):** Report issued to a contractor following a field inspection where one or more deficiencies were found that need to be resolved. A score of 1 or 2 is assigned.

**Pass Report:** Report issued to a contractor following a field inspection where a score of 3, 4, or 5 has been assigned. There may be one or more deficiencies that need to be corrected, but a response in QACSS is not required.

# **Frequently Asked Questions**

#### I'm having trouble logging in to QACSS.

For HPwES contractors who do not participate in the EmPower Program

- Locate the Contractor Welcome Email. If the email cannot be located, contact the HPwES program implementer at <u>contractorsupport@clearesult.com</u> or 1-800-284-9069 (option 2).
- 2. Go to the QACSS login page: <u>https://cris.nyserda.org/qacss/login.aspx</u>.
- 3. Click Forgot Password?.
- 4. Enter the username provided in the Contractor Welcome Email and click Submit.
- 5. The password is emailed to the same email address that was used to send the Contractor Welcome Email.
- 6. Once the password is received, go back to the QACSS login page (see URL above), and enter your username and password.

For HPwES contractors who also participate in the EmPower Program

Companies that participate in both HPwES *and* EmPower need to determine if they want a single login for both programs or two different logins. To make the determination follow these instructions:

- Start by logging into QACSS for EmPower: <u>https://cris.nyserda.org/qacss/login.aspx</u>. Use your company's existing CRIS username and password (the one used to access NYSERDA's database for EmPower). If this doesn't work, contact the Empower program field representative for assistance.
- 2. Once you are able to log in to QACSS from EmPower, click on the EmPower icon in the upper right quadrant of the screen.
  - If a Home Performance drop-down option appears, your company has a single login for both programs. You can easily toggle between the two programs by using this drop-down.
  - If a Home Performance drop-down option does *not* appear, you have two different logins, one for EmPower and one for HPwES. In order to access HPwES, you need to logout of QACSS for EmPower. (To log out, click on your company's name in the upper right corner of the screen, then click Logout.) Once you're logged out, follow the instructions above for HPwES contractors who do *not* participate in the EmPower Program.

### Who do I contact for help with QACSS?

Your program implementer can provide technical support for specific CARs and assist with general system questions.

• Email <u>contractorsupport@clearesult.com</u> or call 1-800-284-9069 (option2)

#### How do I change my contact email for QACSS notifications?

Contact your program implementer.

#### Can I add a user to QACSS?

Each company is assigned one QACSS login per program. This single login can be shared, but additional logins cannot be provided.

#### I can't find a specific customer in my Dashboard or I received an email notification but can't find the customer in QACSS.

- 1. Solution #1: Are you both an HPwES *and* EmPower contractor? If yes, first determine in which program your customer participated. Next, determine if you are logged in to QACSS under the correct program; the program name is listed in the upper right quadrant of the QACSS screen (second bubble from the right).
  - If you are logged in to the wrong program, log out and log back in to the correct program. Please note that if you have the same username for both programs, you can toggle between the two programs (without logging out) by clicking on the program name.
  - If you are already logged in to the correct program and still cannot find your customer, contact the program implementer for assistance.
- 2. Solution #2: Does the body of the email state "No further action is required"?
  - If so, no CAR was issued, and the inspection does not appear in your Dashboard view. To view the inspection results, click on Job Score Reports under the My Work List menu, then locate your customer and open the Job Score Report (JSR).

# I can't download any QA documents, for example: Pass Report, Fail Report, Performance Report.

If you are unable to download documents from QACSS, it is likely you need to disable your pop-up blocker. After disabling the pop-up blocker, try to download the document again.

To allow pop-ups in Google Chrome, look for the pop-up blocker icon at the end of the address bar. The icon looks like this: 2. Right click on the icon and select "Always allow pop-ups on this site."